

Oil Field Environmental Incident Summary

Incident: 20140810130714 **Date/Time of Notice:** 08/10/2014 13:07

Responsible Party: ONEOK Rockies Midstream

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 8/9/2014

Time Incident: 00:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 95

Sec: 17

Qtr: SE SE

Location Description: Sandstone Compressor Station is approximately 17 miles due east of Watford City, ND on Highway 23 on the north side of the highway immediately adjacent to our Blue Buttes Compressor Station.

Submitted By: Mitch Anderson

Received By:

Contact Person: Mitch Anderson
2700 Lincoln Avenue SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	4200	Gallons	4200	Gallons		

Description of Other Released Contaminant:

Methanol

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were/are no immediate health hazards

Areal Extent:

200'L x 6'W

Potential Environmental Impacts:

There were no adverse environmental impacts associated with this release.

Action Taken or Planned:

A vacuum truck was summoned to the scene to remove pooled liquids.

Wastes Disposal Location: The liquids will be transported off-site and transferred into a licensed disposal well.

Agencies Involved: McKenzie Co. LEPC Director

Updates

Date: 8/11/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of methanol on the facility location. This is an NDDoH jurisdiction. Followup is required.

Date: 8/13/2014 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 88 °F, clear, with wind from the southeast 20-25 miles per hour. The methanol tank located next to the compressor building overflowed from the vent due to the pump continuously running. The methanol flowed west to southwest under other structures on site before stopping at the built-up road area. The methanol evaporated; however, the company personnel is having a consultant test the area of the pooling to make sure nothing else needs to be done. More followup needed with personnel on the testing results.

Date: 5/13/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 14:56 p.m. The weather was partly cloudy, 52°F, with the wind from the southeast 5-10 mph. A larger methanol tank has been placed in the containment with the condensate tanks. The tank containment is lined. The site has some erosion issues, but I do not see any other issues at this time. No further followup required. 47.80747; - 102.88383